

United States
Environmental Protection
Agency
Washington DC 20460

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies. *8105-011*

IL. #16 810504

1LS-000-001-347

Name Rockford Coatings Corporation
Street 1620 Harrison Avenue
City Rockford State IL Zip Code 61101

Name of Site Wastex Research, Inc.
Street 2000 Broadway
City East St. Louis County _____ State IL Zip Code 62207

Name (Last, First and Title) Charles Dodge, Plant Superintendent
Phone (815) 962-7768

From (Year) 1979 To (Year) 1980



315987

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☐ Unknown
18. ☐ Other (Specify)

[illegible]

000002 MAY -4 81

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☒ Other (Specify) proposed incineration

Total Facility Waste Amount

cubic feet

gallons

10,000 G**Total Facility Area**

square feet

acres

G Known, Suspected or Likely Releases to the Environment:

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☒ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Rockford Coatings CorporationStreet 1620 Harrison AvenueCity Rockford State IL Zip Code 61101Signature William Blomgren Date 5/3/81(Treasurer)

- ☐ Owner, Present
☐ Owner, Past
☐ Transporter
☒ Operator, Present
☐ Operator, Past
☐ Other

TABLE I

WASTE TYPE	U.S. E.P.A. HAZARDOUS WASTE NO.	HANDLING CODE	QUANTITY	COMPONENTS	FREQUENCY
<u>Listed Wastes</u>					
Spent Halogenated Solvents & Sludges	F001 (T)	T34	1,300 T/yr	LISTED	
Spent Halogenated Solvents & Still Bottoms	F002 (T)	T34	1,300 T/yr	"	
Spent Non-Halogenated Solvents & Still Bottoms	F003 (I)	T34	11,250 T/yr	"	
Spent Non-Halogenated Solvents & Still Bottoms	F005 (I, T)	T34	200 T/yr	"	
Wastewater Treatment Sludges	F006 (T)	T34	200 T/yr	"	
Spent Cyanide Plating Bath Solutions	F007 (R, T)	T34	200 T/yr	"	
Plating Bath Sludges	F008 (R, T)	T34	200 T/yr	"	
Spent Stripping & Cleaning Bath Solution	F009 (R, T)	T34	200 T/yr	"	
Quenching Bath Sludge	F010 (R, T)	T34	200 T/yr	"	
Spent Cyanide Solutions	F011 (R, T)	T34	200 T/yr	"	
Quenching Wastewater Sludges	F012 (T)	T34	200 T/yr	"	
Wastewater Treatment Sludges	K002	T34	20 T/yr	"	
Wastewater Treatment Sludges	K003	T34	20 T/yr	"	
Wastewater Treatment Sludges	K004	T34	20 T/yr	"	
Wastewater Treatment Sludges	K005	T34	20 T/yr	"	
Wastewater Treatment Sludges	K006	T34	20 T/yr	"	
Wastewater Treatment Sludges	K007	T34	20 T/yr	"	
DAF Float - Petroleum Refinery	K048	T34	600 T/yr	"	
Heat Exchanger Cleaning Sludge	K050	T34	1,500 T/yr	"	
API Separator Sludge	K051	T34	1,000 T/yr	"	
Tank Bottoms (Leaded) - Refinery	K052	T34	375 T/yr	"	
Ammonia Still Lime Sludge - Coking	K060 (T)	T34	80 T/yr	"	

↑
Generics

↓ Inorganic
pigments

↓ Petroleum Refining

Materials will be processed soon after received. Transfer from storage will be daily until inventory is depleted.

TABLE I

WASTE TYPE		U.S. E.P.A. HAZARDOUS WASTE NO.	HANDLING CODE	QUANTITY	COMPONENTS	FREQUENCY
<u>Listed Wastes</u>						
Emission Control Dust/Sludge - EF	<i>Iron + Steel</i>	K061 (T)	T34	4,000 T/yr	Listed	Material will be processed soon after received. Transfer from storage will be daily until inventory is depleted.
Spent Pickle Liquor - Steel		K062 (CT)	T34	16,000 T/yr	"	
Emission Control Dust/Sludge - Lead	<i>Secondary Lead</i>	K069 (T)	T34	20 T/yr	"	
<u>Non-Listed Wastes</u>						
Waste Paint	} <i>Ignitable</i>	D001	T34	1,000 T/yr	Mineral Spirits	Material will be transferred from storage for processing only when lot size quantities of 100 tons are available.
Waste Paint Thinner		D001	T34	1,500 T/yr	1	
Ink Wastes		D001	T34	1,000 T/yr	2	
Wash Solvents		D001	T34	1,500 T/yr	3	
Waste Alcohols		D001	T34	1,500 T/yr	Alcohol	
Off-Spec Organic Materials		D001	T34	500 T/yr	4	

44,45 T/yr

1 Naphtha, Aliphatic and Aromatic Hydrocarbons, Ketones.

2 Alcohols, Ketones, Naphtha, Ethers.

3 Naphtha, Aliphatic and Aromatic Hydrocarbons, Alcohols, Ketones, Ethers, Mineral Spirits.

4 Naphtha, Mineral Spirits, Alcohols, Ketones.

Note: T34 Other - Fixation/Solidification.